- Bermuda House

Guideline for Canadian Drinking Water Quality: 10 ug/L

		Lead Concentration ug/L June 2016	
Location ID	Location Description	1st Draw	2nd Draw
Bermuda 1	Don's apartment kitchen	1.70	
Bermuda 2	Don's apartment washroom	0.87	

Value

⁻ Exceeds Health Canada Guidelines for Drinking Water Quality of 10ug/L

- Campbell Hall

Guideline for Canadian Drinking Water Quality: 10 ug/L

			ntration ug/L 2016
Location ID	Location Description	1st Draw	1st Draw 2nd Draw
Campbell 1	Don's apartment kitchen	<0.50	
Campbell 2	Don's apartment bathroom	1.1	
Campbell 3	4th floor - bathroom 1 - Rm. 432	0.87	
Campbell 4	4th floor - bathroom 2 - Rm. 426	0.93	
Campbell 5	4th floor - bathroom 3 - Rm. 418	1.7	
Campbell 6	4th floor - bathroom 4 - Rm. 414	1.1	
Campbell 7	4th floor - bathroom 5 - Rm. 410	0.81	
Campbell 8	4th floor - bathroom 6 - Rm. 406	0.89	
Campbell 9	4th floor - bathroom 7 - Rm. 403	0.94	
Campbell 10	4th floor - bathroom 8 - Rm. 407	0.92	
Campbell 11	4th floor - bathroom 9 - Rm. 411	0.71	
Campbell 12	4th floor - bathroom 10 - Rm. 415	0.82	
Campbell 13	4th floor - bathroom 11 - Rm. 419	0.63	
Campbell 14	4th floor - bathroom 12 - Rm. 423	0.87	
Campbell 15	4th floor - bathroom 13 - Rm. 425	1.3	
Campbell 16	4th floor - bathroom 14 - Rm. 431	0.73	
Campbell 17	4th floor - bathroom 15 - Rm. 435	1.0	
Campbell 18	4th floor - bathroom 16 - Rm. 437	1.2	
Campbell 19	4th floor - bathroom 17 - Rm. 443	0.84	
Campbell 20	4th floor - bathroom 18 - Rm. 447	0.71	
Campbell 21	4th floor - bathroom 19 - Rm. 451	<0.50	
Campbell 22	4th floor - bathroom 20 - Rm. 453	0.73	
Campbell 23	4th floor - bathroom 21 - Rm. 446	1.6	
Campbell 24	4th floor - bathroom 22 - Rm. 440	0.53	
Campbell 25	4th floor - bathroom 23 - Rm. 436	0.80	
Campbell 26	4th floor kitchen	0.52	
Campbell 27	3rd floor - bathroom 1 - Rm. 330	0.87	
Campbell 28	3rd floor - bathroom 2 - Rm. 326	1.0	
Campbell 29	3rd floor - bathroom 3 - Rm. 318	<0.50	
Campbell 30	3rd floor - bathroom 4 - Rm. 314	0.91	
Campbell 31	3rd floor - bathroom 5 - Rm. 310	0.8	
Campbell 32	3rd floor - bathroom 6 - Rm. 306	1.0	
Campbell 33	3rd floor - bathroom 7 - Rm. 303	0.94	
Campbell 34	3rd floor - bathroom 8 - Rm. 307	0.84	
Campbell 35	3rd floor - bathroom 9 - Rm. 311	1.1	
Campbell 36	3rd floor - bathroom 10 - Rm. 315	0.53	
Campbell 37	3rd floor - bathroom 11 - Rm. 319	1.2	
Campbell 38	3rd floor - bathroom 12 - Rm. 323	1.0	
Campbell 39	3rd floor - bathroom 13 - Rm. 325	0.95	
Campbell 40	3rd floor - bathroom 14 - Rm. 331	1.1	
Campbell 41	3rd floor - bathroom 15 - Rm. 335	0.92	
Campbell 42	3rd floor - bathroom 16 - Rm. 337	1.4	
Campbell 43	3rd floor - bathroom 17 - Rm. 343	1.1	
Campbell 44	3rd floor - bathroom 18 - Rm. 347	1.4	
Campbell 45	3rd floor - bathroom 19 - Rm. 349	1.1	
Campbell 46	3rd floor - bathroom 20 - Rm. 353	1.2	
Campbell 47	3rd floor - bathroom 21 - Rm. 346	0.79	
Campbell 48	3rd floor - bathroom 22 - Rm. 340	0.77	
Campbell 49	3rd floor - bathroom 23 - Rm. 336	1.1	

- Campbell Hall

Guideline for Canadian Drinking Water Quality: 10 ug/L

	Le		Lead Concentration ug/L	
		June	2016	
Location ID	Location Description	1st Draw 2	2nd Draw	
Campbell 50	3rd floor kitchen	<0.50		
Campbell 51	2nd floor - bathroom 1 - Rm. 230	0.95		
Campbell 52	2nd floor - bathroom 2 - Rm. 226	1.1		
Campbell 53	2nd floor - bathroom 3 - Rm. 218	0.99		
Campbell 54	2nd floor - bathroom 4 - Rm. 214	1.1		
Campbell 55	2nd floor - bathroom 5 - Rm. 210	0.91		
Campbell 56	2nd floor - bathroom 6 - Rm. 206	0.65		
Campbell 57	2nd floor - bathroom 7 - Rm. 203	1.2		
Campbell 58	2nd floor - bathroom 8 - Rm. 207	0.63		
Campbell 59	2nd floor - bathroom 9 - Rm. 211	0.97		
Campbell 60	2nd floor - bathroom 10 - Rm. 215	0.78		
Campbell 61	2nd floor - bathroom 11 - Rm. 219	1.0		
Campbell 62	2nd floor - bathroom 12 - Rm. 221	0.7		
Campbell 63	2nd floor - bathroom 13 - Rm. 225	0.87		
Campbell 64	2nd floor - bathroom 14 - Rm. 231	1.7		
Campbell 65	2nd floor - bathroom 15 - Rm. 235	1.1		
Campbell 66	2nd floor - bathroom 16 - Rm. 237	0.98		
Campbell 67	2nd floor - bathroom 17 - Rm. 243	0.78		
Campbell 68	2nd floor - bathroom 18 - Rm. 247	1.5		
Campbell 69	2nd floor - bathroom 19 - Rm. 251	1.1		
Campbell 70	2nd floor - bathroom 20 - Rm. 253	0.72		
Campbell 71	2nd floor - bathroom 21 - Rm. 246	0.71		
Campbell 72	2nd floor - bathroom 22 - Rm. 240	0.88		
Campbell 73	2nd floor - bathroom 23 - Rm. 236	0.68		
Campbell 74	2nd floor kitchen	<0.50		
Campbell 75	1st floor - bathroom 1 - Rm. 139 (left public washroom)	2.0		
Campbell 76	1st floor - bathroom 2 - Rm. 132	1.0		
Campbell 77	1st floor - bathroom 3 - Rm. 128	1.0		
Campbell 78	1st floor - bathroom 4 - Rm. 118	<0.50		
Campbell 79	1st floor - bathroom 5 - Rm. 114	0.87		
Campbell 80	1st floor - bathroom 6 - Rm. 110	0.85		
Campbell 81	1st floor - bathroom 7 - Rm. 106	0.63		
Campbell 82	1st floor - bathroom 8 - Rm. 103	0.86		
Campbell 83	1st floor - bathroom 9 - Rm. 107	<0.50		
Campbell 84	1st floor - bathroom 10 - Rm. 111	0.58		
Campbell 85	1st floor - bathroom 11 - Rm. 115	0.52		
Campbell 86	1st floor - bathroom 12 - Rm. 119	1.0		
Campbell 87	1st floor - bathroom 13 - Rm. 123	0.61		
Campbell 88	1st floor - bathroom 14 - Rm. 125	1.1		
Campbell 89	1st floor - bathroom 15 - Rm. 129	1.0		
Campbell 90	1st floor - bathroom 16 - Rm. 133	0.75		
Campbell 91	1st floor - bathroom 17 - Rm. 137	0.99		
Campbell 92	1st floor - bathroom 18 - Rm. 143 (right public washroom)	1.0		
Campbell 93	1st floor kitchen	<0.50		
Campbell 94	Duplicate of Campbell 21	<0.50		
Campbell 95	Duplicate of Campbell 35	0.51		
Campbell 96	Duplicate of Campbell 78	<0.50		

- Centennial Hall

Guideline for Canadian Drinking Water Quality: 10 ug/L

		Lead Concentration ug/L	
		June 2016	
Location	Location Description	1st Draw	2nd Draw
ID	Location Description	15t Diaw	Ziiu Diaw
Centennial 1	Basement kitchen	0.57	
Centennial 2	Second floor kitchenette	1.1	
Centennial 3	Third floor bathroom	8.1	
Centennial 4	Duplicate of Centennial 3	8.5	

Value

- Exceeds Health Canada Guidelines for Drinking Water Quality of 10ug/L

- Colville House

Guideline for Canadian Drinking Water Quality: 10 ug/L

		Lead Concentration ug/L	
		June 2016	
Location	Leastion Description	1 at Duose	2nd Draw
ID	Location Description	1st Draw 2nd	2nd Draw
Colville 1	Main floor - kitchen	1.7	

Value

- Exceeds Health Canada Guidelines for Drinking Water Quality of 10ug/L

- Convocation Hall

Guideline for Canadian Drinking Water Quality: 10 ug/L

		Lead Concentration ug/L	
		June 2016	
Location	Location Description	1ct Drow	2nd Draw
ID	Location Description	1st Draw	Zna Draw
Con Hall 1	Kitchen	3.0	
Con Hall 2	Main floor fountain	<0.50	
Con Hall 3	Duplicate of Con Hall 1	5.3	

⁻ Exceeds Health Canada Guidelines for Drinking Water Quality of 10ug/L

Mount Allison University Potable Water Sampling Program - Crabtree Building

Guideline for Canadian Drinking Water Quality: 10 ug/L

		Lead Concentration ug/L	
		June 2016	
Location ID	Location Description	1st Draw	2nd Draw
Crabtree 1	B04 Washroom.	0.72	
Crabtree 2	B06 Washoom.	0.52	
Crabtree 3	G38 Ladies washroom. Left sink near stall.	1.8	
Crabtree 4	G38 Ladies washroom. Right sink near door.	2.7	
Crabtree 5	G37 Mens washroom. Left sink.	1.5	
Crabtree 6	G37 Mens washroom. Right sink.	1.1	
Crabtree 7	G6 Rat Holding room.	5.1	
Crabtree 8	G2 Washroom.	5.2	
Crabtree 9	G9 Fume hood room.	7.2	
Crabtree 10	G20 Surgery room. Back wall sink.	9.1	
Crabtree 11	G20 Surgery room. Sink closest door.	46	6.4
Crabtree 12	G12 Holding room.	10	
Crabtree 13	G13.	17	2.6
Crabtree 14	G16 Washing.	10	
Crabtree 15	G7 Holding room.	35	1.6
Crabtree 16	Drinking fountain on Main Floor.	<0.50	
Crabtree 17	M4 Ladies washroom. Left sink.	1.6	
Crabtree 18	M4 Ladies washroom. Middle sink.	2.1	
Crabtree 19	M4 Ladies washroom. Right sink.	2.0	
Crabtree 20	M5 Mens washroom. Left sink.	5.1	
Crabtree 21	M5 Mens washroom. Middle sink.	3.0	
Crabtree 22	M5 Mens washroom. Right sink.	3.4	
Crabtree 23	205 Womens washroom. Left sink.	<0.50	
Crabtree 24	205 Womens washroom. Right sink.	<0.50	
Crabtree 25	207 Mens washroom.	0.75	
Crabtree 26	216 Faculty Lounge kitchen sink.	<0.50	
Crabtree 27	303 Womens washroom. Left sink.	2.5	
Crabtree 28	303 Womens washroom. Right sink.	0.97	
Crabtree 29	302 Mens washroom. Left sink.	0.65	
Crabtree 30	302 Mens washroom. Left Sink (did left instead of right)	3.9	
Crabtree 31	318 Reading Room.	3.4	
Crabtree 32	Duplicate of Crabtree 23	<0.50	
Crabtree 33	Duplicate of Crabtree 28	1.4	

- Exceeds Health Canada Guidelines for Drinking Water Quality of 10ug/L