

**Mount Allison University Potable Water Sampling Program  
- Dunn Building**

Guideline for Canadian Drinking Water Quality: 5 ug/L

Location ID	Location Description	Lead Concentration ug/L	
		17-May	
		1st Reading	2nd Reading
Dunn 1	1st floor - fountain	<0.1	
Dunn 2	109 A female washroom sink 2 (left)	0.9	
Dunn 3	109 A female washroom sink 1 (right)	0.4	
Dunn 4	1st floor male washroom	0.3	
Dunn 5	2nd floor - kitchenette (Room 228)	0.1	
Dunn 6	219 A male washroom	0.2	
Dunn 7	219 B female washroom	0.3	
Dunn 8	315 A female washroom sink 1 (Left)	0.7	
Dunn 9	315 A female washroom sink 2 (Right)	1.0	
Dunn 10	315 B male washroom	0.3	
Dunn 11	411 A female washroom sink 1 (Left)	1.8	
Dunn 12	411 A female washroom sink 2	8.7	0.3
Dunn 13	411 B Male washroom	0.2	

**Value** - Exceeds Health Canada Guidelines for Drinking Water Quality of 5ug/L

## Mount Allison University Potable Water Sampling Program - Edwards House

Guideline for Canadian Drinking Water Quality: 5 ug/L

Location ID	Location Description	Lead Concentration ug/L	
		17-May	
		1st Reading	2nd Reading
Edwards 1	3rd floor - bathroom 1 (307 Right sink)	0.9	
Edwards 2	3rd floor - bathroom 2 (307 Left sink)	1.0	
Edwards 3	3rd floor - bathroom 3 (316 Right)	1.3	
Edwards 4	3rd floor - bathroom 4 (316 Left)	1.0	
Edwards 5	3rd floor - bathroom 5 (318 Right)	1.2	
Edwards 6	3rd floor - bathroom 6 (318 Left)	1.6	
Edwards 7	3rd floor - bathroom 7 (329 Right)	2.3	
Edwards 8	3rd floor - bathroom 8 (329 Left)	1.9	
Edwards 9	3rd floor - kitchen 1 (327)	0.3	
Edwards 10	3rd floor - kitchen 2 (315)	0.4	
Edwards 11	2nd floor - bathroom 1 (229 Right)	4.4	
Edwards 12	2nd floor - bathroom 2 (229 Left)	1.0	
Edwards 13	2nd floor - bathroom 3 (218 Right)	0.7	
Edwards 14	2nd floor - bathroom 4 (218 Left)	1.2	
Edwards 15	2nd floor - bathroom 5 (216 Right)	2.8	
Edwards 16	2nd floor - bathroom 6 (216 Left)	1.7	
Edwards 17	2nd floor - bathroom 7 (207 Right)	1.1	
Edwards 18	2nd floor - bathroom 8 (207 Left )	4.6	
Edwards 19	2nd floor - kitchen 1 (215)	0.7	
Edwards 20	2nd floor - kitchen 2 (227)	0.3	
Edwards 21	1st floor - bathroom 4 (107 Right)	2.7	
Edwards 22	1st floor - bathroom 5 (107 Left)	1.2	
Edwards 23	1st floor - bathroom 6 (118 Right)	1.9	
Edwards 24	1st floor - bathroom 7 (118 Left)	1.4	
Edwards 25	1st floor - bathroom 8 (120 Right)	6.4	0.4
Edwards 26	1st floor - bathroom 9 (120 Left)	2.1	
Edwards 27	1st floor - kitchen 1 (132)	0.5	
Edwards 28	1st floor - kitchen 2 (110)	0.3	
Edwards 29	Basement kitchen (G13)	0.3	
Edwards 30	Staff Bathroom (rm G12)	3.3	
Edwards 31	Bathroom G17 Sink left	0.9	
Edwards 32	Bathroom G17 Sink right	4.8	
Edwards 33	Dons apartment kitchen	0.2	
Edwards 34	Dons apartment washroom	2.7	

**Value**

- Exceeds Health Canada Guidelines for Drinking Water Quality of 5ug/L

## Mount Allison University Potable Water Sampling Program - Facilities Management Building

Guideline for Canadian Drinking Water Quality: 5 ug/L

Location ID	Location Description	Lead Concentration ug/L	
		17-May	
		1st Reading	2nd Reading
FM 1	Kitchen 110	0.6	0.6
FM 2	Main floor men's washroom	2.4	2.4
FM 3	Main floor women's washroom	3.0	3.0
FM 4	Ground floor washroom	0.8	0.8
FM 5	Kitchen G8	0.2	0.2
FM 6	Plumbing Shop	2.0	2.0
FM 7	Kitchen Heating Plant	0.7	0.7

**Value** - Exceeds Health Canada Guidelines for Drinking Water Quality of 5ug/L

**Mount Allison University Potable Water Sampling Program  
- Fawcett Building**

Guideline for Canadian Drinking Water Quality: 5 ug/L

Location ID	Location Description	Lead Concentration ug/L	
		17-May	
		1st Reading	2nd Reading
Fawcett 1	Grounds shop - Kitchen	0.3	
Fawcett 2	Grounds shop - Bottle filler	<0.1	
Fawcett 3	Grounds shop- Water fountain	<0.1	

**Value**

- Exceeds Health Canada Guidelines for Drinking Water Quality of 5ug/L

**Mount Allison University Potable Water Sampling Program  
-Flemington Building**

Guideline for Canadian Drinking Water Quality: 5 ug/L

LocationID	Location Description	Lead Concentration	
		17-May 1st Reading	2nd Reading
Flemington 1	Drinking fountain first floor.	<0.1	
Flemington 2	Kitchen sink, second floor staff room (room 107). Coffee machine on counter.	<b>126.0</b>	0.8
Flemington 3	Second floor bathroom sink. Single person bathroom, beside room 205.	3.8	
Flemington 4	Ladies washroom room 10. Sink on left.	1.5	
Flemington 5	Ladies washroom room 10. Sink on right.	1.5	
Flemington 6	Men's washroom Room 9. Sink on left.	1.7	
Flemington 7	Men's washroom Room 9. Sink on right.	1.0	
Flemington 8	Washroom room 208.	3.6	
Flemington 9	Men's Washroom room 313 sink.	<b>6.2</b>	0.2
Flemington 10	Women's Washroom room 314 sink.	2.4	
Flemington 11	Department Head's office	<b>5.7</b>	1.7
Flemington 12	Bathroom sink, room 206	4.0	

**Value**

- Exceeds Health Canada Guidelines for Drinking Water Quality of 5ug/L